

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-023538**Date Inspected:** 09-May-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** ShangHai, China**CWI Name:** Shi Yu**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

Summary of Items Observed: On this date Caltrans OSM Quality Assurance(QA) Inspector, DJ Shin was present during the times noted above for observations relative to the work being performed.

**Bay 10**

This QA inspector performed Ultrasonic Testing (UT) of approximately 10 % of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member(s) is/are identified as follows; BK009A5-001 on item number 2, of NWIT tracker document # 09077,

**Loading Dock and Deck of Ship**

This QA Inspector observed the following work in progress for loading dock.

ZPMC perform SMAW welding for OBG 12 and Tower Lift 6 supporting jig on the top of vessel. around 56 workers working on the OBG 12East and West for touch up painting, grinding, Load bike path, tie down, Etc., ZPMC loading crew has loaded 17 bike paths, 1 cross beam and OBG 12 East and West Tower Lift 6 and Numbers of steel barriers.

This QA inspector performed Magnetic Particle Testing (MT) and Visual Inspection (VT) of approximately 15 % of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member(s) is/are identified as follows; OBG 12, on item number 4 of NWIT tracker document # 09080,

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

documents.



## Summary of Conversations:

No relevant conversations

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Shin,DJ	Quality Assurance Inspector
<b>Reviewed By:</b>	Riley,Ken	QA Reviewer

---